




FIG. 1



WIRING PROCESS



CUTTING



ASSEMBLY PROCESS

FIG.2A




FIG.2B




FIG.2C




FIG.3A




FIG.3B




FIG.4




FIG.5




FIG.6A




FIG.6B




FIG. 7A




FIG. 7B




FIG.8




FIG. 9




FIG.10






FIG. 11




FIG.12




FIG.13




FIG.14




FIG.15




FIG.16




FIG.17A




FIG.17B




FIG.18




FIG.19




FIG.20




FIG.21






FIG.22A




FIG.22C




FIG.22B




FIG.22D




FIG.23A




FIG.23B




FIG.24A




FIG.24B




FIG.25A




FIG.25B




FIG.26A




FIG.26B




FIG.27A




FIG.27B




FIG.28A




FIG.28B




FIG.29






FIG.30A




FIG.30B




FIG.31




FIG.32




FIG.33




FIG.34




FIG.35




FIG.36




FIG.37

